

State Water Resources Control Board

June 7, 2016

(Via email and Certified Mail)

CERTIFIED MAIL
NO. 7015 1520 0001 8019 6507

Mr. Douglas Coble
General Manager
Redding Jet Center
3775 Flight Avenue
Redding, California 96002
doug@reddingjet.com

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS
LOCATED AT REDDING JET CENTER, 3775 FLIGHT AVENUE, REDDING**

Dear Mr. Coble:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on May 25, 2016, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Tank Lining Test Results – The tank lining inspection test results were not available at the time of inspection.	All	May 25, 2016	Ongoing	H&SC 25293; 23 CCR 2712(b), 2715(e)
2	Failure to Maintain Cathodic Protection Test Results – The cathodic protection test results were not available at the time of inspection.	All	May 25, 2016	Ongoing	H&SC 25293; 23 CCR 2712(b), 2715(e)
3	Failure to Monitor Product Piping – The piping sump sensors are not able to detect a leak at the earliest possible opportunity because the sensors were not located at the lowest position in the sump.	T2, T3, T4	May 25, 2016	Ongoing	23 CCR 2630(d)

No.	Violation	Tank	Start Date	Stop Date	Regulation
4	Failure to Maintain Monitoring Records On-Site – The 2013 and 2014 monitoring certification records were not available at the time of the inspection.	All	May 25, 2016	Ongoing	23 CCR 2712(b)
5	Failure to Maintain Financial Responsibility – The financial responsibility certification form was not available at the time of inspection.	All	May 25, 2016	Ongoing	H&SC 25292.2; 23 CCR 2711(a)(11)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Shasta County Environmental Health Division within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Mr. Thomas Henderson
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
1001 I Street, 16th Floor
Sacramento, California 95814
tom.henderson@waterboards.ca.gov

Local CUPA

Mr. Kevin Westlake
Environmental Health Specialist
Shasta County Environmental Health
1855 Placer Street, Suite 201
Redding California, 96001
kwestlake@co.shasta.ca.us

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: see next page

cc: *(via email only)*

Mr. Kevin Westlake
Shasta County Environmental Health Division
kwestlake@co.shasta.ca.us